

dimLED Kabel mini
USB to DMX

Thank you for choosing to use our product
Please read carefully the manual before using.

Feature:

- (1) USB DMX Interface.
- (2) Micro processor enabled.
- (3) Supports Various 3rd party softwares.
- (4) Internal frame buffering.
- (5) Drivers for Windows.
- (6) DMX512 times configurable.
- (7) Support Windows XP、 Vista、 Windows7(32bit and 64bit)

This works for example with:
Freestyler

If you want to know more,please refer to the disc’s video、 Freestyler software "help menu"、 www.freestylersupport.com、 [www.youtube.cometc](http://www.youtube.com/etc).

Install 1 (Apply to Windows XP、 Vista、 Windows7)

- 1、 Insert the usb to dmx interface device to computer USB port.
- 2、 The computer detect find out new device hardware.
- 3、 Select the computer ,click the right mouse button,choose"device Manager".


- 4、 You can see the"udmx"icon is yellow exclamation point.
- 5、 Click the "udmx",choose update driver software.
- 6、 On the pop up window ,choose "browse my computer for driver software".
- 7、 Select the location of the drive directory from the cd disk.
- 8、 Click next to install,if computer has pop-up prompt window,then choose "install this driver software anyway"
- 9、 After successful installation,in the device Manager"udmx"icon is without yellow exclamation point,it mean USB to dmx interface device successful installation.
- 10、 Install the computer software - Freestyler

The above installation steps , you can also watch the installation video which on the cd disk.


Install 2 (Apply to Windows7、 Window8、 Windows10)

Note:The driver can only be installed in some window8、 Windows10 system version,whether the installation success depends on your computer and system version.


- Windows7
- 1.Open **Start/Run**
 - 2.Write "**gpedit.msc**"(without inverted commas)[1]and press“OK”[2]
 - 3.On the next screen select: "**User Confi guration**"[1]/"**Administrative Templates**"[2]/"**System**"[3]/"**Driver Installation**"[4]



4.Right click on "**Code Signing for Device Drivers**"and select"**Edit**"




5.In the "**Code Signing for Device Drivers**"window,choose"**Enabled**"[1]and "**Warn**"[2]and click"**Apply**", "**OK**"[3].




6.Restart your computer to install unsigned drivers.

Windows 8 and Windows 10


1.Right click on **Start**[1]and choose **Run** [2]




2.Write "**shutdown.exe/r/o/f/t 00**" (Note the space bar) (without inverted commas)[1]and press"**OK**"[2]




3.Wait for System restart.Press"**Troubleshoot**" on the next screen.




4.Press"**Advanced Options**" on the next screen.



5.Press"**Start-up Settings**" on the next screen.



5.Press"**Restart**" on the next screen.



7.Wait for System restart.Press **F7** kye to"Disable Driver Signature Enforcement"



8.Wait for the cmplete Syste restart.

Then fllo the above"Install 1"to complete driver installation.