


1


Power OFF



2


Adjust to the suitable power

Set the appropriate phase





3

Option 1: No-dimming



Option 2: Dimming



No copper contact

With copper contact

4

①

②

5

power on

